CAPSULE SUMMARY - HANCE BARN'B' (CT-1030)

Hance Barn 'B' is located in Huntingtown on a 19th century farm that includes a tobacco barn and house. The 24 x 40 foot aisle plan barn is oriented on a north-south axis and is located in a hollow on the east side of the main farm road. The barn is of modern construction employing circular sawn materials and wire nails. The most striking feature of this barn is the presence of a hayloft above the south half of the barn. The barn is supported by a heavy timber frame system on concrete blocks and is sheathed with vertical blanks.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	e (indic	ate prefer	ced name)				
historic							
and/or common	William	Hance Jr.	Tobacco E	Barn B	**		
2. Loca	ition						
street & number	2725 Holl	ands Clif	fs Rd.			_ not for publ	ication
city, town Hunt	ingtown	e.	vicinity of	congressional	district		
state MD	• • •		cou	nty Calvert			
3. Clas	sificatio	on					
Category district building(s) structure site object	Ownership public × private both Public Acquis in process being cons _ not appli	ition Ac	atus occupied unoccupied work in progre cessible yes: restricted yes: unrestrict	entertain governm	re ial nal ment ent	museun park private r religious scientifi transpo	residence s c
4. Own	er of Pr	operty	(give name	s and mailing ad	dresses	of <u>all</u> ow	ners)
name Willia	ım Hance Jr	•					
street & number	2725 Holl	ands Clif	fs Rd.	telep	hone no.	.:301-535	-0748
city, town	Hungtingt	own	sta	ate and zip code	MD 20	0639	
5. Loca	tion of	Legal	Descrip	tion			
courthouse, regis	stry of deeds, etc	Calvert	County Cour	thouse		liber ^{abo}	e 329
street & number			eet (MD 765)		folio	622
ci ty , town		Prince F	rederick		state	Maryland	
6. Repr	'esenta	tion in	Existin	g Historical	Surve	ys	
title							
date				federal	state	county	loca
apository for su	rvey records		ANNING & ZONI				-
city, town		PRINCE FRED		0678	state		

Survey No. CT-1030

Condition		Check one	Check one		
excellent good fair	deteriorated ruins unexposed	unaltered _X_ altered	X original s	ite date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Hance barn B is located on the north side of Holland's Cliffs Road. The barn is associated with a surrounding farm divided among the members of the Hance family. The farm house dates to the mid-nineteenth century, and there is one mid-nineteenth century tobacco barn also located on the property, on the western side of the principal farm road from Barn B.

This barn is located across the farm road to the east of Barn A and is oriented on a north-south axis. The barn measures twenty-four by forty feet and has no sheds. The plan is an aisle plan. Both the original barn twenty-four by twenty-four feet (Section A) and the sixteen foot addition (Section B) are of modern construction, employing circular sawn lumber and wire nails. The existence of a hay loft area is evidence of the multi-use of this barn. The aisle plan is indicative of the contemporary date of the structure.

The barn is divided into three major components. The two ground-floor components consist of a twenty-four by twenty-four foot room and a sixteen by twenty-four foot component connected by one door. Both of these sections are designed for curing tobacco. There is an upper story above section A which is floored and used for hay storage. The structural system of section B is entirely separate from section A and was built at a later time. Section B, unlike section A, has no floor and is used to hang tobacco throughout. There are four doors into the barn, three on the ground level, and one on the second story to allow entry into loft area. Two of these ground-level entrances are located along the gable ends of the structure. The one facade entrance is centered along the west wall of section B.

1600- 1700- 1800-	archeology-historic X agriculture architecture art	community planning conservation	literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:A		EFG	
	Level of Significance:	_nationalstate	local	
Prepare support	both a summary paragraph (of significance and	a general statement o	f history and

Survey No. CT-1030

This structure is of modern construction post-dating 1880. The use of peeled log poles suggests a pre-1940' date, but this is not definitive. The toe-nailed joints, light timbers and wire nails confirm this date. The evidence of multi-use in this structure is striking, as the second story of section A was built as a hay loft and has never been used for curing tobacco.

Historic Period theme(s): Twentieth century

Geographic organization:

8. Significance

Chronological/Developmental Period: Twentieth Century

Resource Type(s): Tobacco Barn, Hay loft

The barn was erected near the older barn on the property and the specific purpose of hay storage was fulfilled in addition to tobacco curing. The addition was presumably built at a somewhat later date. Nailers were added to section A and the addition was supported in this fashion. The fact that this barn was constructed and expanded during the twentieth century represent the expansion of the tobacco industry during this period. It is no longer used for tobacco.

10. Geographical Data	
Acreage of nominated property Quadrangle name Benedict, MD UTM References do NOT complete UTM references	Quadrangle scale 1:24000
A	Zone Easting Northing
C	D
Verbal boundary description and justification List all states and counties for properties overlapping	estato ou county houndaries
	unty code
state code co	unty code
11. Form Prepared By	
name/title Tora L. Williamsen-Berry	
organization c/o Calvert County Historic District Commission	date June 30, 1990
street & number Dept. of Planning and Zoni	ng telephone ³ 01-535-1600
Courthouse city or town Prince Frederick	state ^{MD}

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401


(301) 269-2438

Hance Barn B

7. DESCRIPTION (CONT.)

Section A contains eight rooms and is divided into three eightfoot bays. Section B is divided into two eight foot bays. Concrete blocks support the structure. Relatively light circular sawn timbers on continuous sills form the frame of this structure. Down braces occur in each bay in Section B and along the end bays in section A. The original sill from section A where it intersects with section B now creates a cross sill between the two sections. Joints are primarily toe-nailed. The upper story of Section A is completely floored (supported by large joists 8' above ground) and used for hay storage. The entire barn is sheathed in vertical wall siding and has minimal ventilation. The metal roofing is supported by rafters on four foot centers which rest on a flat false plate. Peeled log poles run down the axis ten feet from the west side of both sections and help to hang the tobacco. The poles in Section A also serve to support the flooring.

BARN # 2003 NEW HANCE BARN 2/21/90 tw 1":10" NA CT-1030 DOUR DOOR Poem a securite p All used following Shedded Room 1 above Only lower room used for poor





Northmest